

| Type Designation | Maker or Originator | CV No. (or nearest in brackets) | Type Designation | Maker or Originator | CV No. (or nearest in brackets) | Type Designation | Maker or Originator | CV No. (or nearest in brackets) |
|---|---|---|------------------|-------------------------------|----------------------------------|------------------|---------------------|---------------------------------|
| DH13-10 DH13-97 DH30 | Mullard Mullard MOV | (CV5811) (CV5168) (CV1695) | DMS17 | Dynamco | CV9278(o)/ (CV7438) | | | |
| DH63 DH63M DH73M DH77 DH81 | MOV MOV MOV | (CV587) CV2909 (CV452) (CV882) | DMS20 | Dynamco Dynamco Dynamco | CV9277(o)/ (CV7492) CV9371 | | | |
| DH147 DH150 DHM9-11 DHM10-93 DH/PM 17036-1 | Mullard Mullard De Havilland | (CV1055) (CV3882) CV8108 CV5369 CV5891 | DMS25T | Dynamco | Spec/QPL | | | |
| DH/PM 17036-2 DK1 DK10 DK13 DK32 | De Havilland Mullard STC STC Mullard | CV5892 CV2910 CV9077 CV9451 (CV1802) | DMS31 | Dynamco | Spec/QPL | | | |
| DK91 DK92 DK96 DL DLS10 | Mullard Mullard Mullard MOV Ediswan | (CV782) CV5172 CV9026 (CV1661) (CV190) | DMS32 | Dynamco | Spec/QPL | | | |
| DL2 DL33 DL35 DL63 DL64 DL66 DL68 DL69 DL70 DL71 DL72 | Mullard Mullard Mullard MOV QPL Mullard QPL Mullard Mullard Mullard Mullard | CV2911 (CV819) (CV1803) CV2912 (CV2331) (CV2106) (CV2259) (CV2361) (CV2105) (CV385) (CV387) | DMS35 | Dynamco | Spec/QPL | | | |
| DL73 DL75 DL91 DL92 | QPL QPL Mullard QPL | (CV2299) (CV2102) (CV783) { (CV820) CV2370 | DMS37 | Dynamco | Spec/QPL | | | |
| DL93 DL94 DL95 | Mullard Mullard Mullard | (CV807) CV2983 (CV818) | DMS39 | Dynamco | Spec/QPL | | | |
| DL98 | QPL | (CV2240) | DN7-11 | Mullard | CV10339 | | | |
| DL620 DM6 DM70 | QPL 20th CE Mullard, Philips | (CV2238) (CV2146) CV2980 | DNM9-11 | Mullard | CV5883 (CV1040) | | | |
| DM160 | QPL | { CV5412 (CV6094) | DO24 | Mullard | (CV1178) | | | |
| DMS2I | Dynamco | CV9272(o) (CV7432) | DO26 | Mullard | (CV1178) | | | |
| DMS3I | Dynamco | CV9274(o)/ (CV7438) | DO30 | Mullard | (CV1206) | | | |
| DMS5/1 DMS5/2 DMS8 | Mullard Mullard Dynamco | CV8785 CV8786 CV9275(o)/ (CV7041), CV7369 | DO60 | Mullard | (CV11074) | | | |
| DMS9 | Dynamco | CV9276(o)/ (CV7040) | DO47695 | Texas | (CV11074) | | | |
| DMS10 | Dynamco | CV9273(o)/ (CV7340) | DP4-1 | Mullard | CV5940 | | | |
| DMS12 | Dynamco | CV9271(o)/ (CV7324, 3, 6, CV7151) | DP7-5 | Mullard | CV5171 | | | |
| | | | DP7-11 | Mullard | CV9509 | | | |
| | | | DP13-2 | Mullard | CV5157 | | | |
| | | | DP13-97 | Mullard | CV5760 | | | |
| | | | DP16-22 | QPL | (CV2498) | | | |
| | | | DPM9-11 | Mullard | CV9284 CV8109 | | | |
| | | | DQP | Cossor | (CV1121) | | | |
| | | | DS | Ferranti | (CV2979) | | | |
| | | | DS1E | Ferranti | (CV7190) | | | |
| | | | DS1F | Ferranti | (CV7191) | | | |
| | | | DS1G | Ferranti | (CV7192) | | | |
| | | | DS3 | Ferranti | CV8945 | | | |
| | | | DS103 | MWT | (CV94) | | | |
| | | | DI70 | USA | (CV798(o)) | | | |
| | | | DI1003 | Lucas | CV9238 | | | |
| | | | DI1013 | Lucas | CV10693 | | | |
| | | | DI1121 | Lucas | CV9965 | | | |
| | | | DI1122 | Lucas | CV9353 | | | |
| | | | DI1520 | Lucas | CV8989 | | | |
| | | | DI1521 | Lucas | CV9194 | | | |
| | | | DI1612 | Lucas | CV9523 | | | |
| | | | DI4112(o) | Lucas | CV9966 | | | |
| | | | DT4306 | Lucas | CV10844 | | | |
| | | | DI6106 | Lucas | CV10875 | | | |
| | | | DIS413 | Delco | CV10447 | | | |
| | | | DTS423 | Delco | CV9905 | | | |
| | | | DV32 | STC | (CV88) | | | |
| | | | DV34 | STC | (CV127) | | | |
| | | | DV40B | STC | (CV228) | | | |
| | | | DV55 | STC | (CV230) | | | |
| | | | DV56 | STC | (CV234) | | | |
| | | | DW2 | Mullard | (CV1443) | | | |
| | | | DW4/350 | Mullard | CV1796 | | | |
| | | | DW4/500 | Mullard | (CV1064) | | | |
| | | | DY70 | Mullard | (CV2241) | | | |
| | | | DY86 | Mullard | CV10708 | | | |
| | | | DY87 | Mullard | CV10761 | | | |