

CV9695-CV9784

CV9695	2N2646;	COM	Unijunction Transistor	CV9740	1N1490;	MIL	Transistor
CV9696	1N3029B;	COM	Zener Diode	CV9741	2N1488;	MIL	Transistor
CV9697	2N3108;	COM	Transistor	CV9742	2N1483;	MIL	Transistor
CV9698	16F10;	COM	Semiconductor Rectifier	CV9743	1N963B;	MIL	Zener Diode
CV9699	2N2369;	COM	Transistor	CV9744	1N831A;	MIL	Semiconductor Diode
CV9700	2N1147B;	COM	Transistor	CV9745	1N754A;	MIL	Zener Diode
CV9701	2N3501;	COM	Transistor	CV9746	1N746A;	MIL	Zener Diode
CV9702	2N3637;	COM	Transistor	CV9747	1N663;	MIL	Semiconductor Diode
CV9703	2N1052;	COM	Transistor	CV9748	1N647;	MIL	Semiconductor Rectifier
CV9704	C66;	COM	Transistor	CV9749	1N3039B;	MIL	Zener Diode
CV9705	2N3503;	COM	Transistor	CV9750	1N3038B;	MIL	Zener Diode
CV9706	2N3375;	COM	Transistor	CV9751	1N3002B;	MIL	Zener Diode
CV9707	2N3478;	COM	Transistor	CV9752	1N3001RB;	MIL	Zener Diode
CV9708	BZY91-C10R;	COM	Zener Diode	CV9753	1N2997B;	MIL	Zener Diode
CV9709	25HB10;	COM	Semiconductor Rectifier	CV9754	1N2988B;	MIL	Zener Diode
CV9710	25HBR10;	COM	Semiconductor Rectifier	CV9755	1S5036C/Y413; CV7295;	COM	Zener Clipper Diode
CV9711	1N4511;	COM	Semiconductor Rectifier	CV9756	1S5068C/Y413; CV7302;	COM	Zener Clipper Diode
CV9712	1N914;	MIL	Semiconductor Diode	CV9757	1S5091C/Y413; CV7305;	COM	Zener Clipper Diode
CV9713	L4757;	COM	Microwave Switch	CV9758	1S5018C/Y413; CV7288;	COM	Zener Clipper Diode
CV9714	Cancelled	COM		CV9759	1S5033C/Y413; CV7294;	COM	Zener Clipper Diode
CV9715	1N3730;	COM	Semiconductor Diode	CV9760	ZT1483/CV7455	MOA	Transistor
CV9716	2N3419;	COM	Transistor	CV9761	ZT1484/CV7456	MOA	Transistor
CV9717	2N1506A;	COM	Transistor	CV9762	ZT1485/CV7457	MOA	Transistor
CV9718	2N2887;	COM	Transistor	CV9763	ZT1486/CV7458	MOA	Transistor
CV9719	ZT2876;	COM	Transistor	CV9764	DET3; CV1034;	COM	Triode
CV9720	FD6004;	COM	Transistor	CV9765	DD4066;	COM	Semiconductor Rectifier
CV9721	HS9001;	COM	Semiconductor Diode	CV9766	2N656;	COM	Transistor
CV9722	1IC7005B;	COM	Var. Cap. Diode	CV9767	2N174A	COM	Transistor
CV9723	1S021;	COM	Semiconductor Rectifier	CV9768	1N3028B;	COM	Zener Diode
CV9724	BSY28;	COM	Transistor	CV9769	1N1124A;	COM	Semiconductor Rectifier
CV9725	HG1086;	COM	Semiconductor Diode (Quads)	CV9770	1N1742A;	COM	Zener Diode
CV9726	5907;	MIL	Pentode	CV9771	TCR74;	COM	Thyristor
CV9727	7761;	COM	Pentode	CV9772	CG61-H;	COM	Semiconductor Diode
CV9728	6216;	MIL	Pentode	CV9773	G100J;	COM	Semiconductor Rectifier
CV9729	MA4298;	COM	Var. Cap. Diode	CV9774	E3000;	COM	Transistor (Darlington Pair)
CV9730	ASY26;	COM	Transistor	CV9775	E3001;	COM	Transistor (Darlington Pair)
CV9731	1N1234;	COM	Semiconductor Rectifier	CV9776	353-1174-00; 566-9192-002	COM	Zener Diode
CV9732	GN4D;	COM	Numerical Indicator	CV9777	AD161/AD162;	COM	Transistor
CV9733	090-001483; Y260 (Mod.);	COM		CV9778	AC127;	COM	Transistor
CV9734	2N342;	MIL	Transistor	CV9779	AC128;	COM	Transistor
CV9735	2N341;	MIL	Transistor	CV9780	BC107; CV1000	COM	Transistor
CV9736	2N332;	MIL	Transistor	CV9781	2N1487B;	COM	Thyristor
CV9737	2N333;	MIL	Transistor	CV9782	10D2;	COM	Semiconductor Rectifier
CV9738	7895;	MIL	Triode	CV9783	322PS124;	COM	Transistor
CV9739	1N3611;	MIL	Semiconductor Rectifier	CV9784	BZX19;	COM	Zener Diode